


MADE TO MEASURE

WORMS AND WHEELS

From
1+>

A FACE requires machining?
Need a PRECISION gear?
Send us your drawings!



TIP: to determine the orientation of the helix angle, lay the gear flat on a table.
If the teeth rise to the right, the gear has a right hand helix angle.
If the teeth rise to the left, the gear has a left hand helix angle.